

SYNERGY ELECTRIC BICYCLE.

16 FEB 2013

BOUGHT FOR \$300

BATTERIES LIKELY BAD.

MISSING FRONT BRAKE PADS

OPENED BATT PACK - 1/8" HEX KEY NEEDED

SOME OF HOUSING CRACKED

INSIDE, 2X UB12120 12V 12AH LEAD ACID BATT.

IN SERIES, NO CHARGER CIRCUITRY.



EACH BATT SHOWING 0.3 VOLTS

BIKE DID NOT COME W/ CHARGER.

SELLER MIGHT FIND IT & CONTACT ME.

40A BLADE FUSE INSIDE

CHARGER PORT (OUTSIDE)



PIN LOOSE ON QUICK CONNECT FOR CHARGING PORT